

IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 10004119-3

IN RE APPLICATION OF: U.S. Patent No. 7,103,793

USPTO CONFIRMATION CODE: 7688

APPLICATION NO.: 10/685,940

FILED: Oct. 14, 2003

EXAMINER: Hong Kim

GROUP ART UNIT: 2185

FOR: MEMORY CONTROLLER HAVING RECEIVER CIRCUITRY CAPABLE OF ALTERNATELY GENERATING ONE OR MORE DATA STREAMS AS DATA IS RECEIVED AT A DATA PAD, IN RESPONSE TO COUNTS OF STROBE EDGES RECEIVED AT A STROBE PAD

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/685,940, now Patent Number 7,103,793.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to Deposit Account No. 082025.

All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In column 5, line 61, insert - - DDR - - before "SDRAMs".
(Specification filed on Oct. 14, 2003, page 10, line 1)


In column 22, line 16, delete "/1;2" and insert - - 1/2 - -, therefor.
(Specification filed on Oct. 14, 2003, page 38, line 20)

In column 22, line 33, delete "DQS18 RCV_ON" and
insert - - DQS18_RCV_ON - -, therefor.
(Specification filed on Oct. 14, 2003, page 39, line 3)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

12/16/2008
DATE


Name: Steven L. Webb
Registration No.: 44,395

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY
Intellectual Property Administration
P.O. Box 272400
Fort Collins, Colorado 80527-2400

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,103,793

APPLICATION NO. : 10/685,940

ISSUE DATE : Sep. 05, 2006

INVENTOR(S) : Eric M. Rentschler, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 5, line 61, insert - - DDR - - before "SDRAMs".

In column 22, line 16, delete "/1;2" and insert - - 1/2 - -, therefor.

In column 22, line 33, delete "DQS18 RCV_ON" and insert - - DQS18_RCV_ON - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY
Intellectual Property Administration
P. O. Box 272400
Fort Collins, Colorado 80527-2400

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.